



State of New Hampshire
DEPARTMENT OF ENVIRONMENTAL SERVICES

6 Hazen Drive, P.O. Box 95, Concord, NH 03302-0095
(603) 271-3406 FAX (603) 271-7894



June 12, 2002
Letter of Deficiency
DAM #209.20

Ms. Marilyn Campbell
Turner Homestead Inc.
79 Brady Avenue
Salem, NH 03079

RE: Campbell Golf Course Pond 12A Dam, Salem

Dear Ms. Campbell

The Department of Environmental Services, Dam Bureau (DES) consistently strives to enhance the safety of dams in New Hampshire through its dam safety program. One of the many instruments that plays a part in reaching this goal is our inspection program. DES is forwarding this correspondence to you to advise you that in accordance with RSA 482:12 and Env-Wr 502.02, an inspection of the subject dam was conducted on May 17, 2001. During this visual inspection and/or file review, the following deficiencies were observed:

There was no visible downstream end to the outlet in the wetland area at the toe of the dam; and

- 2 There was no operation and maintenance plan on file with the DES.

DES believes that the above deficiencies can be corrected by performing the following items by the indicated schedule:

August 1, 2002:

1. Prepare and submit to the DES a written operational procedure plan. The plan should describe the control of impoundment levels, monitoring and maintenance procedures, and identify emergency contact personnel; and
2. Locate the downstream end of the low-level outlet pipe and maintain the area clear of brush and debris.

DES is requesting that you complete and submit the attached "Intent to Complete Repairs" form, within 30 days of receipt of this letter, that will provide for correction of the identified deficiencies by the date(s) indicated above. If you believe changes to the items of work or dates are necessary, please make the changes directly on the form and provide a brief explanation. We have enclosed a self addressed stamped envelope for you to return this form.

Our intent in sending you this correspondence is to make you aware of items that DES believes warrant your attention to insure the continued safe operation of your dam. It is our hope that, through the submittal of the attached form and a commitment to keeping a well-maintained dam, you will voluntarily comply with the requested items of work. If we do not receive the intent form or a similarly adequate written reply, we will assume that you are in agreement with our findings and recommendations and DES will carry out follow-up inspections accordingly.

Letter of Deficiency
Dam #209.20
June 12, 2002
pg. 2

If you have any questions or comments regarding this Letter of Deficiency or would like to be present at future inspections, please contact me at 271-3406, or write to the Water Division at the address listed on the top of the previous page.

Sincerely,


COPY
Grace E. Levergood, P.E.
Dam Safety Engineer

Attachments Guideline for an O&M plan, DB13

cc: Gretchen Rule ✓

Town of Salem

Certified # 7099 3400 0002 9773 8419

GEL/was/h:/safety/wendy/lod/209-20lod.doc